Fig.1




Fig.2




Fig.3




Fig.4 (A)




Fig.4 (B)




Fig.5




Fig.6(A)






Fig.6 (B)








Fig.7(C)

128a

128e

128e

Fig.8




Fig.9




Fig.10(A)




Fig.10(B)




Fig.10(C)




Fig.11






Fig.12








Fig.14(A)

Fig. 15






Fig. 16










Fig.19




Fig.20








Fig.21









[After Engine is Warmed Up]




Fig.26




Fig.27




Fig. 28




Fig.29




Fig.30




Fig.31




Fig.32




Fig.33

